The information provided here is for informational and educational purposes and current as of the date of publication. The information is not a substitute for legal advice and does not necessarily reflect the opinion or policy position of the Municipal Association of South Carolina.

Consult your attorney for advice concerning specific situations.




wsp		
	Topics	
	 Audit expectations How to prepare for an audit 	
	 Common deficiencies found during audits 	
	 How to highlight continuous improvement in your program 	
	Potential audit results	
March 7, 2024	What to do after an audit	
SCASM		
2		











2







<page-header><page-header><page-header><section-header><section-header><section-header>










wsp	
	Common Deficiencies Found During Audits
	Illicit Discharge Detection and Elimination Illegal sewer connection
2013M Mich'/ 2014	
14	

wsp	Common Deficiencies Found During Audits	
	Illicit Discharge Detection and Elimination	
	Evidence of paint poured down storm drain	
SCLSM March 1,2034		
15		







wsp

Common Deficiencies Found During Audits

Management of Construction Site Runoff
 Lack of BMP maintenance/improperly installed





<image><image><list-item><list-item><list-item><list-item><list-item><section-header>










wsp					
	Common Deficiencies Found During Audits				
	Plan Reviews				
	Not enforcing requirements for permitting Larger Common Plans				
	 Not meeting water quality/quantity requirements for each and every outfall leaving site (not combined) 				
	 Not meeting post-dev <!--= pre-dev peak flow rates for -->2 acre projects 				
	 Not meeting 80% trapping efficiency for sites >10 acres 				
	 Not addressing post-construction water quality for sites > 5 acres 				
á	 Post-construction water quality based on impervious surfaces vs. 1 inch over total drainage area 				
March 7, 2024	 Lack of phased land disturbance for >5 acres (2 phases) and >10 acres (3 phases) 				
έψ.	 Not meeting undisturbed buffer (30ft/45ft) 				
SCASM	Lack of maintenance agreement or unsigned				
scy	Lack of/incomplete checklist				
25	Lack of as-built				



9